


## Jumbo Temperature & RH Indicator



### Specifications

Temp Range	: 0 – 70 Deg C
RH Range	: 0 to 100% RH
Display	: 2" RED LED
Resolution	: 0.1 Deg c for temperature ,1 % for RH
Accuracy	: 0.3 Deg C ,2% RH
Calibration	: Thro Zero & Span Trim port.
Power Supply	: 230 V ac
Size	: 450 *185* 50 mm